

Tecnical data sheet 12-11

DETERGENTE: CLEANER for CNX ADHESIVE

Cleaning of surfaces to be glued

Use Cleaner only on dry and cleaned surfaces

For thorough cleaning use fast dye crepe paper soaked with cleaner.

Always use a new piece of paper for each cleaning operation.

Any condensation should be removed before applying glue

In order to clean insulating pipes it is advisable to use a cloth soaked with cleaner.

Cleaning of tools

Dip brushes into the cleaner for a few minutes and dry them well before applying glue with them

Special remarks

Be aware the working area with Cleaner (and glue) is completely free of open fires and potential sources of sparks.

The product is flammable.

Keep container in a well ventilated place

Before starting any welding work, make sure all solvent vapours are removed from pipe systems, workrooms and ducts..

Follow safety instructions concerning flammable substances.

Warnings and suggestions

Do not breathe the vapours.

Do not swallow the product.

Avoid the contact with skin and eyes.

Do not expose to freezing conditions.

Max shelf life 18 months

Specific weight : 0,80 Kg/Lt

Storage temperature in original sealed packaging +10°C - +40°C

Packing

Cans 1 Lt 12 pieces for cartoon

Cans 5 Lt 4 pieces for cartoon

Our informations come from our best experiences and knowledge and do not constitute obligations or responsibility by our company



UNION FOAM S.P.A.

VIA DELL'INDUSTRIA, 11

20882 BELLUSCO (MB) ITALY

tel. 00 39 – 039 62089.1 Fax 00 39 – 039 6840849

<http://www.unionfoam.it> E-mail: sales@unionfoam.it